


Bender
Repair
5 Mar 24
①



Rationale

Can't get the 1/2" out of the west end of the 5/8".
 Also won't be able to get the 2 3/8" overlap of the 5/8 out of the 3/4".
 Must also assume won't be able to get the 2 3/8" overlap of the 3/4 out of the 7/8".
 Must rebuild entire element side.

1. Use on hand 1" tubing to refurbish the part next to the beam.
2. Build element, working toward the tip of lengths to match existing element.

Parts ordered to Ling Tues, 5 Mar. \$ 133.21.